


To whom it may concern

It is certified that there is sufficient safe drinking water facility and sanitary installation is also in good condition in the school campus of Kendriya Vidyalaya Nadaun, Tehsil Nadaun, District Hamirpur (H.P).

No. JSV-NSD-A-1(50)/2024-25- 14

Dated:- 8/4/2024


Assistant Engineer
Jal Shakti Vibhag
Sub Division Nadaun